



Work Approval Form

Customer Chip Harrey Aircraft # N761K Work Order # _____

Item #	205 #	Description	Estimated Cost		Priority	Work Approved	
			Parts	Labor		Yes	No
1.		Autopilot inop					
2.		Cabin Pressure leak at 14,000 (10,000 ft. cabin)					
3.		Co pilot altitude indicator inop					
4.		Hobbs meter inop					
5.		Weather radar inop					
6.		Power levers split, 2"					
7.		Right hand wing fuel gage inop					
8.		Right hand nav light fence missing					
9.		Both taxi lights inop					
10.		Audio master ticking with engines off					
11.		Chin light behind pilot will not turn off					
12.		Ner 2, (tied to HSI copilot) only works on half the frequencies					
13.		Copilot mic switch inop					
14.		Supercharger needs servicing					
15.		Cabin door stair cable broken					

Cutter Form 203a (02/01/04)

Computer Generated

Please note that tax, freight, and consumables have not been included in this estimate. Consumables are based on 5% of the total labor, not to exceed \$500.00. Over and above charges may apply on cores after evaluation by the vendor.